

PHOTO 09 / TEST SQUARE

ROOFING / ROOF SURFACE

Roof overview documenting the inspected roof area and general field conditions.



PHOTO 10 / HAIL DAMAGE

ROOFING / ROOF SURFACE

Chalk-marked hail damage documented on the roof surface during the property inspection for claim-scope review.



PHOTO 21 / ROOF OVERVIEW

ROOFING / ROOF SURFACE

Roof overview documenting the inspected roof area and general field conditions.



PHOTO 22 / WIND DAMAGE

ROOFING / ROOF SURFACE

Wind-creased shingle consistent with uplift damage.